

Replacement Sheet



Fig 3A.






Fig 3B.



BEST AVAILABLE CO



Replacement Sheet



440

Fig 4.

BEST AVAILABLE COPY



Replacement Sheet




FIG. 5

BEST AVAILABLE COPY



Replacement Sheet




Fig. 6A

SEM Micrograph of Group B at 300x after Electrochemical Test.




Fig. 6B

SEM Micrograph of Group B at 700x after electrochemical test.

~~SECRET~~ AVAILABLE COPY

Replacement Sheet




Fig. 7A




Fig. 7B

SEM micrographs of the Hayes CrCoMo sample after ASTM F746
corrosion test indicates intergranular corrosion attacks.

BEST AVAILABLE COPY



Replacement Sheet




Fig. 7C




Fig. 7D

SEM micrographs of the Hayes CrCoMo sample after ASTM F746
corrosion test exhibiting corrosion attacks.

BEST AVAILABLE COPY



Replacement Sheet




Fig. 8A




Fig. 8B

SEM micrographs of the Hayes CrCo sample prior to any corrosion test.